

CHAPTER 12

HANDTOOLS AND MEASURING DEVICES

INTRODUCTION

This chapter contains information on some of the handtools used by an aviation mechanic. It outlines the basic knowledge required in using the most common handtools and measuring instruments used in aircraft repair work. This information, however, cannot replace sound judgment on the part of the individual. There are many times when ingenuity and resourcefulness can supplement the basic rules. A sound knowledge is required of these basic rules and of the situations in which they apply. The use of tools may vary, but good practices for safety, care, and storage of tools remain the same.

GENERAL-PURPOSE TOOLS

Hammers and Mallets

Figure 12-1 shows some of the hammers that the aviation mechanic may be required to use. Metal-head hammers are usually sized according to the weight of the head without the handle.

Occasionally it is necessary to use a soft-faced hammer, which has a striking surface made of wood, brass, lead, rawhide, hard rubber, or plastic.




FIGURE 12-1. Hammers.

These hammers are intended for use in forming soft metals and striking surfaces that are easily damaged. Soft-faced hammers should not be used for rough work. Striking punch heads, bolts, or nails will quickly ruin this type hammer.

A mallet is a hammerlike tool with a head made of hickory, rawhide, or rubber. It is handy for shaping thin metal parts without denting them. Always use a wooden mallet when pounding a wood chisel or a gouge.

When using a hammer or mallet, choose the one best suited for the job. Ensure that the handle is tight. When striking a blow with the hammer, use the forearm as an extension of the handle. Swing the hammer by bending the elbow, not the wrist. Always strike the work squarely with the full face of the hammer.

Always keep the faces of hammers and mallets smooth and free from dents to prevent marring the work.

Screwdrivers

The screwdriver can be classified by its shape, type of blade, and blade length. It is made for only one purpose, i.e., for loosening or tightening screws or screwhead bolts. Figure 12-2 shows several different types of screwdrivers. When using the common screwdriver, select the largest screwdriver whose blade will make a good fit in the screw which is to be turned.

A common screwdriver must fill at least 75 percent of the screw slot. If the screwdriver is the wrong size, it cuts and burrs the screw slot, making it worthless. A screwdriver with the wrong size blade may slip and damage adjacent parts of the structures.

The common screwdriver is used only where slotted head screws or fasteners are found on aircraft. An example of a fastener which requires the use of a common screwdriver is the airlock fastener which is used to secure the cowling on some aircraft.

The two types of recessed head screws in common use are the Phillips and the Reed and Prince.




FIGURE 12-2. Typical screwdrivers.

Both the Phillips and Reed and Prince recessed heads are optional on several types of screws. As shown in figure 12-2, the Reed and Prince recessed head forms a perfect cross. The screwdriver used with this screw is pointed on the end. Since the Phillips screw has a slightly larger center in the cross, the Phillips screwdriver is blunt on the end. The Phillips screwdriver is not interchangeable with the Reed and Prince. The use of the wrong type screwdriver results in mutilation of the screwdriver and the screwhead. When turning a recessed head screw, use only the proper recessed head screwdriver of the correct size.

An offset screwdriver may be used when vertical space is limited. Offset screwdrivers are constructed with both ends bent 90° to the shank handle. By using alternate ends, most screws can

be seated or loosened even when the swinging space is limited. Offset screwdrivers are made for both standard and recessed head screws.

A screwdriver should not be used for chiseling or prying. Do not use a screwdriver to check an electric circuit since an electric arc will burn the tip and make it useless. In some cases, an electric arc may fuse the blade to the unit being checked.

When using a screwdriver on a small part, always hold the part in the vise or rest it on a workbench. Do not hold the part in the hand, as the screwdriver may slip and cause serious personal injury.

The ratchet or spiral screwdriver is fast acting in that it turns the screw when the handle is pulled back and then pushed forward. It can be set to turn the screw either clockwise or counterclockwise, or it can be locked in position and used as a standard screwdriver. The ratchet screwdriver is not a heavy-duty tool and should be used only for light work. A word of caution: When using a spiral or ratchet screwdriver, extreme care must be used to maintain constant pressure and prevent the blade from slipping out from the slot in the screw head. If this occurs, the surrounding structure is subject to damage.

Pliers and Plier Type Cutting Tools

There are several types of pliers, but those used most frequently in aircraft repair work are the diagonal, adjustable combination, needlenose, and duckbill. The size of pliers indicates their overall length, usually ranging from 5 to 12 inches.

The 6-inch slip-joint plier, is the preferred size for use in repair work. The slip-joint permits the jaws to be opened wider at the hinge for gripping objects with large diameters. Slip-joint pliers come in sizes from 5 to 10 inches. The better grades are drop-forged steel.

Flatnose pliers are very satisfactory for making flanges. The jaws are square, fairly deep, and usually well matched, and the hinge is firm. These are characteristics which give a sharp, neat bend.

Roundnose pliers are used to crimp metal. They are not made for heavy work because too much pressure will spring the jaws, which are often wrapped to prevent scarring the metal.

Needlenose pliers have half-round jaws of varying lengths. They are used to hold objects and make adjustments in tight places.

Duckbill pliers resemble a "duck's bill" in that the jaws are thin, flat, and shaped like a duck's bill. They are used exclusively for twisting safety wire.

Water pump (channel locks) pliers are slip-joint pliers with the jaws set at an angle to the handles.

The most popular type has the slip-joint channeled, hence the name channel locks. These are used to grasp packing nuts, pipe, and odd shaped parts.

Diagonal pliers are usually referred to as diagonals or "dikes." The diagonal is a short-jawed cutter with a blade set at a slight angle on each jaw. This tool can be used to cut wire, rivets, small screws, and cotter pins, besides being practically indispensable in removing or installing safety wire. The duckbill pliers and the diagonal cutting pliers are used extensively in aviation for the job of safety wiring.

Two important rules for using pliers are:

1. Do not make pliers work beyond their capacity. The longnosed variety are especially delicate. It is easy to spring or break them, or nick the edges. If this occurs, they are practically useless.
2. Do not use pliers to turn nuts. In just a few seconds, a pair of pliers can damage a nut more than years of service.

Punches

Punches are used to locate centers for drawing circles, to start holes for drilling, to punch holes in sheet metal, to transfer location of holes in patterns, and to remove damaged rivets, pins, or bolts.




FIGURE 12-3. Punches.

Solid or hollow punches are the two types generally used. Solid punches are classified according to the shape of their points. Figure 12-3 shows several types of punches.

Prick punches are used to place reference marks on metal. This punch is often used to transfer dimensions from a paper pattern directly on the metal. To do this, first place the paper pattern directly on the metal. Then go over the outline of the pattern with the prick punch, tapping it lightly with a small hammer and making slight indentations on the metal at the major points on the drawing. These indentations can then be used as reference marks for cutting the metal. A prick punch should never be struck a heavy blow with a hammer because it may bend the punch or cause excessive damage to the material being worked.

Large indentations in metal, that are necessary to start a twist drill, are made with a center punch. It should never be struck with enough force to dimple the material around the indentation or to cause the metal to protrude through the other side of the sheet. A center punch has a heavier body than a prick punch and is ground to a point with an angle of about 60°.

The drive punch, which is often called a tapered punch, is used for driving out damaged rivets, pins, and bolts which sometimes bind in holes. The drive punch is therefore made with a flat face instead of a point. The size of the punch is determined by the width of the face, which is usually 1/8 inch to 1/4 inch.

Pin punches, often called drift punches, are similar to drive punches and are used for the same purposes. The difference in the two is that the sides of a drive punch taper all the way to the face while the pin punch has a straight shank. Pin punches are sized by the diameter of the face, in thirty-seconds of an inch, and range from 1/16 to 3/8 inch in diameter.

In general practice, a pin or bolt which is to be driven out is usually started and driven with a drive punch until the sides of the punch touch the side of the hole. A pin punch is then used to drive the pin or bolt the rest of the way out of the hole. Stubborn pins may be started by placing a thin piece of scrap copper, brass, or aluminum directly against the pin and then striking it with a hammer until the pin begins to move.

Never use a prick punch or center punch to remove objects from holes, because the point of the

punch will spread the object and cause it to bind even more.

The transfer punch is usually about 4 inches long. It has a point that tapers, then turns straight for a short distance in order to fit a drill-locating hole in a template. The tip has a point similar to that of a prick punch. As its name implies, the transfer punch is used to transfer the location of holes through the template or pattern to the material.

Wrenches

The wrenches most often used in aircraft maintenance are classified as open-end, box-end, socket, adjustable, and special wrenches. The allen wrench, although seldom used, is required on one special type of recessed screw. One of the most widely used metals for making wrenches is chrome-vanadium steel. Wrenches made of this metal are almost unbreakable.

Solid, nonadjustable wrenches with open parallel jaws on one or both ends are known as open-end wrenches. These wrenches may have their jaws parallel to the handle or at an angle up to 90° ; most are set at an angle of 15° . Basically, the wrenches are designed to fit a nut, bolthead, or other object which makes it possible to exert a turning action.

Box-end wrenches are popular tools because of their usefulness in close quarters. They are called box wrenches since they box, or completely surround, the nut or bolthead. Practically all box-end wrenches are made with 12 points so they can be used in places having as little as 15° swing. In figure 12-4, point A on the illustrated double broached hexagon wrench is nearer the center line of the head and the wrench handle than point B, and also the center line of nut C. If the wrench is inverted and installed on nut C, point A will be centered over side "Y" instead of side "X". The center line of the handle will now be in the dotted line position. It is by reversing (turning the wrench over) the position of the wrench that a 15° arc may be made with the wrench handle.

Although box-end wrenches are ideal to break loose tight nuts or pull tight nuts tighter, time is lost turning the nut off the bolt once the nut is broken loose. Only when there is sufficient clearance to rotate the wrench in a complete circle can this tedious process be avoided.

After a tight nut is broken loose, it can be completely backed off or unscrewed more quickly with an open-end than with a box-end wrench. In this case, a combination wrench is needed, which has a box-end on one end and an open-end wrench of




FIGURE 12-4. Box-end wrench use.

the same size on the other. Both the box-end and combination wrenches are shown in figure 12-5.

A socket wrench is made of two parts: (1) The socket, which is placed over the top of a nut or bolthead, and (2) a handle, which is attached to the socket. Many types of handles, extensions, and attachments are available to make it possible to use socket wrenches in almost any location or position. Sockets are made with either fixed or detachable handles. Socket wrenches with fixed handles are usually furnished as an accessory to a machine. They have either a four-, six- or twelve-sided recess to fit a nut or bolthead that needs regular adjustment.

Sockets with detachable handles usually come in sets and fit several types of handles, such as the T, ratchet, screwdriver grip, and speed handle. Socket wrench handles have a square lug on one end that fits into a square recess in the socket head. The two parts are held together by a light spring-loaded poppet. Two types of sockets, a set of handles, and an extension bar are shown in figure 12-6.




FIGURE 12-5. Box end and combination wrenches.

The adjustable wrench is a handy utility tool which has smooth jaws and is designed as an open-end wrench. One jaw is fixed, but the other may be moved by a thumbscrew or spiral screwworm adjustment in the handle. The width of the jaws may be varied from 0 to $\frac{1}{2}$ inch or more. The angle of the opening to the handle is $22\frac{1}{2}^\circ$ on an adjustable wrench. One adjustable wrench does the work of several open-end wrenches. Although versatile, they are not intended to replace the standard open-end, box-end, or socket wrenches. When using any adjustable wrench, always exert the pull on the side of the handle attached to the fixed jaw of the wrench.

Special Wrenches

The category of special wrenches includes the spanner, torque, and allen wrenches. The hook spanner is for a round nut with a series of notches cut in the outer edge. This wrench has a curved arm with a hook on the end which fits into one of the notches on the nut. The hook is placed in one of these notches with the handle pointing in the direction the nut is to be turned.

Some hook spanner wrenches are adjustable and will fit nuts of various diameters. U-shaped hook spanners have two lugs on the face of the wrench to fit notches cut in the face of the nut or screw plug. End spanners resemble a socket wrench but have a series of lugs that fit into corresponding notches in a nut or plug. Pin spanners have a pin in place of a lug, and the pin fits into a round hole in the edge of a nut. Face pin spanners are similar to the U-shaped hook spanners except that they have pins instead of lugs.

There are times when definite pressure must be applied to a nut or bolt. In such cases a torque




FIGURE 12-6. Socket wrench set.

wrench must be used. The torque wrench is a precision tool consisting of a torque-indicating handle and appropriate adapter or attachments. It measures the amount of turning or twisting force applied to a nut, bolt, or screw.

The three most commonly used torque wrenches are the deflecting beam, dial-indicating, and micrometer-setting types. When using the deflecting beam and the dial-indicating torque wrenches, the torque is read visually on a dial or scale mounted on the handle of the wrench. The micrometer-setting torque wrench is preset to the desired torque. When this torque is reached, a sharp impulse or breakaway is noticed by the operator.

Before each use, the torque wrench should be visually inspected for damage. If a bent pointer, cracked or broken glass (dial type), or signs of rough handling are found, the wrench must be tested. Torque wrenches must be tested at periodic intervals to ensure accuracy.

Most headless setscrews are the allen type and must be installed and removed with an allen wrench. Allen wrenches are six-sided bars in the shape of an L. They range in size from $\frac{3}{64}$ to $\frac{1}{2}$ inch and fit into a hexagonal recess in the setscrew.

METAL CUTTING TOOLS

Hand Snips

There are several kinds of hand snips, each of which serves a different purpose. Straight, curved, hawksbill, and aviation snips are in common use (figure 12-7). Straight snips are used for cutting straight lines when the distance is not great enough to use a squaring shear and for cutting the outside of a curve. The other types are used for cutting the inside of curves or radii. Snips should never be used to cut heavy sheet metal.

Aviation snips are designed especially for cutting heat-treated aluminum alloy and stainless steel. They are also adaptable for enlarging small holes. The blades have small teeth on the cutting edges and are shaped for cutting very small circles and irregular outlines. The handles are the compound leverage type, making it possible to cut material as thick as 0.051 inch. Aviation snips are available in two types, those which cut from right to left and those which cut from left to right.

Unlike the hacksaw, snips do not remove any material when the cut is made, but minute fractures often occur along the cut. Therefore, cuts should be made about one-thirty-second inch from the layout line and finished by hand-filing down to the line.




FIGURE 12-7. Snips.

Hacksaws

The common hacksaw has a blade, a frame, and a handle. The handle can be obtained in two styles, pistol grip and straight (figure 12-8).

Hacksaw blades have holes in both ends; they are mounted on pins attached to the frame. When installing a blade in a hacksaw frame, mount the blade with the teeth pointing forward, away from the handle.

Blades are made of high-grade tool steel or tungsten steel and are available in sizes from 6 to 16 inches in length. The 10-inch blade is most commonly used. There are two types, the all-hard blade and the flexible blade. In flexible blades, only the teeth are hardened. Selection of the best




FIGURE 12-8. Hacksaws.

blade for the job involves finding the right type and pitch. An all-hard blade is best for sawing brass, tool steel, cast iron, and heavy cross-section materials. A flexible blade is usually best for sawing hollow shapes and metals having a thin cross section.

The pitch of a blade indicates the number of teeth per inch. Pitches of 14, 18, 24, and 32 teeth per inch are available. A blade with 14 teeth per inch is preferred when cutting machine steel, cold-rolled steel, or structural steel. A blade with 18 teeth per inch is preferred for solid stock aluminum, bearing metal, tool steel, and cast iron. Use a blade with 24 teeth per inch when cutting thick-walled tubing, pipe, brass, copper, channel, and angle iron. Use a 32-teeth-per-inch blade for cutting thin-walled tubing and sheet metal.

When using a hacksaw, observe the following procedures:

1. Select an appropriate saw blade for the job.
2. Assemble the blade in the frame so that the cutting edge of the teeth points away from the handle.
3. Adjust tension of the blade in the frame to prevent the saw from buckling and drifting.
4. Clamp the work in the vise in such a way that will provide as much bearing surface as possible and will engage the greatest number of teeth.
5. Indicate the starting point by nicking the surface with the edge of a file to break any sharp corner that might strip the teeth. This mark will also aid in starting the saw at the proper place.
6. Hold the saw at an angle that will keep at least two teeth in contact with the work at all times. Start the cut with a light, steady, forward stroke just outside the cutting line. At the end of the stroke, relieve the pressure and draw the blade back. (The cut is made on the forward stroke.)
7. After the first few strokes, make each stroke as long as the hacksaw frame will allow. This will prevent the blade from overheating. Apply just enough pressure on the forward stroke to cause each tooth to remove a small amount of metal. The strokes should be long and steady with a

speed not more than 40 to 50 strokes per minute.

8. After completing the cut, remove chips from the blade, loosen tension on the blade, and return the hacksaw to its proper place.

Chisels

A chisel is a hard steel cutting tool which can be used for cutting and chipping any metal softer than the chisel itself. It can be used in restricted areas and for such work as shearing rivets, or splitting seized or damaged nuts from bolts (figure 12-9).




FIGURE 12-9. Chisels.

The size of a flat cold chisel is determined by the width of the cutting edge. Lengths will vary, but chisels are seldom under 5 inches or over 8 inches long.

Chisels are usually made of eight-sided tool steel bar stock, carefully hardened and tempered. Since the cutting edge is slightly convex, the center portion receives the greatest shock when cutting, and the weaker corners are protected. The cutting angle should be 60° to 70° for general use, such as for cutting wire, strap iron, or small bars and rods.

When using a chisel, hold it firmly in one hand. With the other hand, strike the chisel head squarely with a ball-peen hammer.

When cutting square corners or slots, a special cold chisel called a cape chisel should be used. It is like a flat chisel except the cutting edge is very narrow. It has the same cutting angle and is held and used in the same manner as any other chisel.

Rounded or semicircular grooves and corners which have fillets should be cut with a roundnose chisel. This chisel is also used to recenter a drill which has moved away from its intended center.

The diamond point chisel is tapered square at the cutting end, then ground at an angle to provide the sharp diamond point. It is used for cutting B-grooves and inside sharp angles.

Files

Most files are made of high-grade tool steels that are hardened and tempered. Files are manufactured in a variety of shapes and sizes. They are known either by the cross section, the general shape, or by their particular use. The cuts of files must be considered when selecting them for various types of work and materials.

Files are used to square ends, file rounded corners, remove burrs and slivers from metal, straighten uneven edges, file holes and slots, and smooth rough edges.

Files have three distinguishing features: (1) Their length, measured exclusive of the tang (figure 12-10); (2) their kind or name, which has reference to the relative coarseness of the teeth; and (3) their cut.

Files are usually made in two types of cuts, single-cut and double-cut. The single-cut file has a single row of teeth extending across the face at an angle of 65° to 85° with the length of the file. The size of the cuts depends on the coarseness of the file. The double-cut file has two rows of teeth which cross each other. For general work, the angle of the first row is 40° to 45° . The first row is

generally referred to as "overcut," and the second row as "upcut"; the upcut is somewhat finer and not so deep as the overcut.

Files—Care and Use

Files and rasps are cataloged in three ways:

Length. Measuring from the tip to the heel of the file. The tang is never included in the length.

Shape. Refers to the physical configuration of the file (circular, rectangular, or triangular or a variation thereof).

Cut. Refers to both the character of the teeth or the coarseness; rough, coarse and bastard for use on heavier classes of work and second cut, smooth and dead smooth for finishing work.

Most Commonly Used Files (see figure 12-11)

Hand files. These are parallel in width and tapered in thickness. They have one safe edge (smooth edge) which permits filing in corners, and on other work where a safe edge is required. Hand files are double-cut and used principally for finishing flat surfaces and similar work.




FIGURE 12-10. Hand file.

Flat files. These files are slightly tapered toward the point in both width and thickness. They cut on both edges as well as on the sides. They are the most common files in use. Flat files are double-cut on both sides and single-cut on both edges.

Mill files. These are usually tapered slightly in thickness and in width for about one-third of their length. The teeth are ordinarily single-cut. These files are used for drawfiling and to some extent for filing soft metals.

Square files. These files may be tapered or blunt and are double-cut. They are used principally for filing slots and key seats, and for surface filing.

Round or rattail files. These are circular in cross section and may be either tapered or blunt and single- or double-cut. They are used principally for filing circular openings or concave surfaces.

Triangular and Three-square files. These files are triangular in cross section. Triangular files are single-cut and are used for filing the gullet between saw teeth. Three-square files, which are double-cut, may be used for filing internal angles, clearing out corners, and filing taps and cutters.

Half-round files. These files cut on both the flat and round sides. They may be single- or double-cut. Their shape permits them to be used where other files would be unsatisfactory.

Lead float files. These are especially designed for use on soft metals. They are single-cut and are made in various lengths.

Warding file—Rectangular in section and tapers to narrow point as to width. Used for narrow space filing where other files cannot be used.

Knife file—Knife-blade section. Used by tool and die makers on work having acute angles.

Wood file—Same section as flat and half round files. Has coarser teeth and is especially adaptable for use on wood.

Vixen (Curved tooth files)—Curved tooth files are especially designed for rapid filing and smooth finish on soft metals and wood. The regular cut is adapted for tough work on cast iron, soft steel, copper, brass, aluminum, wood, slate, marble, fibre, rubber, etc. The fine cut gives excellent results on steel, cast iron, phosphor bronze, white brass, and all hard metals. The smooth cut is used where the amount of material to be removed is very slight, but where a superior finish is desired.




FIGURE 12-11. Types of files.

The following methods are recommended for using files:

1. *Crossfiling.* Before attempting to use a file, place a handle on the tang of the file. This is essential for proper guiding and safe use. In moving the file endwise across the work (commonly known as crossfiling), grasp the handle so that its end fits into and against the fleshy part of the palm with the thumb lying along the top of the handle in a lengthwise direction. Grasp the end of the file between the thumb and first two fingers. To prevent undue wear, relieve the pressure during the return stroke.

2. *Drawfiling.* A file is sometimes used by grasping it at each end, crosswise to the work, then moving it lengthwise with the work. When done properly, work may be finished somewhat finer than when crossfiling with the same file. In drawfiling, the teeth of the file produce a shearing effect. To accomplish this shearing effect, the angle at which the file is held with respect to its line of movement varies with different files, depending on the angle at which the teeth are cut. Pressure should be relieved during the backstroke.

3. *Rounding Corners.* The method used in filing a rounded surface depends upon its width and the radius of the rounded surface. If the surface is narrow or only a portion of a surface is to be rounded, start the forward stroke of the file with the point of the file inclined downward at approximately a 45° angle. Using a rocking chair motion, finish the stroke with the heel of the file near the curved surface. This method allows use of the full length of the file.

4. *Removing Burred or Slivered Edges.* Practically every cutting operation on sheet metal produces burrs or slivers. These must be removed to avoid personal injury and to prevent scratching and marring of parts to be assembled. Burrs and slivers will prevent parts from fitting properly and should always be removed from the work as a matter of habit.

Lathe filing requires that the file be held against the work revolving in the lathe. The file should not be held rigid or stationary but should be stroked constantly with a slight gliding or lateral motion along the work. A standard mill file may be used for this operation, but the long angle lathe file provides a much cleaner shearing and self-clearing action. Use a file with "safe" edges to protect work with shoulders from being marred.

Care of Files

There are several precautions that any good craftsman will take in caring for his files.

1. Choose the right file for the material and work to be performed.
2. Keep all files racked and separated so they do not bear against each other.
3. Keep the files in a dry place—rust will corrode the teeth points.
4. Keep files clean—Tap the end of the file against the bench after every few strokes, to loosen and clear the filings. Use the file card to keep files clean—a dirty file is a dull file.

Particles of metal collect between the teeth of a file and may make deep scratches in the material being filed. When these particles of metal are lodged too firmly between the teeth and cannot be removed by tapping the edge of the file, remove them with a file card or wire brush (figure 12-12). Draw the brush across the file so that the bristles pass down the gullet between the teeth.




FIGURE 12-12. File card.

Drills

There are generally four types of portable drills used in aviation for holding and turning twist drills. Holes $\frac{1}{4}$ inch in diameter and under can be drilled using a hand drill. This drill is commonly called an "egg beater." The breast drill is designed to hold larger size twist drills than the hand drill. In addition a breast plate is affixed at the upper end of the drill to permit the use of body weight to increase the cutting power of the drill. Electric and pneumatic power drills are available in various shapes and sizes to satisfy almost any requirement.

Pneumatic drills are preferred for use around flammable materials, since sparks from an electric drill are a fire or explosion hazard.

Twist Drills

A twist drill is a pointed tool that is rotated to cut holes in material. It is made of a cylindrical hardened steel bar having spiral flutes (grooves) running the length of the body, and a conical point with cutting edges formed by the ends of the flutes.

Twist drills are made of carbon steel or high-speed alloy steel. Carbon steel twist drills are satisfactory for the general run of work and are relatively inexpensive. The more expensive high-speed twist drills are used for the tough materials such as stainless steels. Twist drills have from one to four spiral flutes. Drills with two flutes are used for most drilling; those with three or four flutes are used principally to follow smaller drills or to enlarge holes.




FIGURE 12-13. Twist drill.




FIGURE 12-14. Drills.

The principal parts of a twist drill are the shank, the body, and the point, illustrated in figure 12-13. The drill shank is the end that fits into the chuck of a hand or power drill. The two shank shapes most commonly used in hand drills are the straight shank and the square or bit stock shank (figure 12-14). The straight shank generally is used in hand, breast, and portable electric drills; the square shank is made to fit into a carpenter's brace. Tapered shanks generally are used in machine shop drill presses.

The metal column forming the core of the drill is the body. The body clearance area lies just back of the margin, slightly smaller in diameter than the margin, to reduce the friction between the drill and the sides of the hole. The angle at which the drill point is ground is the lip clearance angle. On standard drills used to cut steel and cast iron, the angle should be 59° from the axis of the drill. For faster drilling of soft materials, sharper angles are used.

The diameter of a twist drill may be given in one of three ways: (1) By fractions, (2) letters, or (3) numbers. Fractionally, they are classified by sixteenths of an inch (from $\frac{1}{16}$ to $3\frac{1}{2}$ in.), by thirty-seconds (from $\frac{1}{32}$ to $2\frac{1}{2}$ in.), or by sixty-fourths (from $\frac{1}{64}$ to $1\frac{1}{4}$ in.). For a more exact measurement a letter system is used with decimal equivalents: A (0.234 in.) to Z (0.413 in.). The number system of classification is most accurate: No. 80 (0.0314 in.) to No. 1 (0.228 in.). Drill sizes

and their decimal equivalents are shown in figure 12-15.

The twist drill should be sharpened at the first sign of dullness. For most drilling, a twist drill with a cutting angle of 118° (59° on either side of center) will be sufficient; however, when drilling soft metals, a cutting angle of 90° may be more efficient.

Typical procedures for sharpening drills (figure 12-16) are as follows:

1. Adjust the grinder tool rest to a convenient height for resting the back of the hand while grinding.
2. Hold the drill between the thumb and index finger of the right or left hand. Grasp the body of the drill near the shank with the other hand.
3. Place the hand on the tool rest with the center line of the drill making a 59° angle with the cutting face of the grinding wheel. Lower the shank end of the drill slightly.
4. Slowly place the cutting edge of the drill against the grinding wheel. Gradually lower the shank of the drill as you twist the drill in a clockwise direction. Maintain pressure against the grinding surface only until you reach the heel of the drill.
5. Check the results of grinding with a gage to determine whether or not the lips are the same length and at a 59° angle.

Reamers

Reamers are used to smooth and enlarge holes to exact size. Hand reamers have square end shanks so that they can be turned with a tap wrench or similar handle. The various types of reamers are illustrated in figure 12-17.

A hole that is to be reamed to exact size must be drilled about 0.003- to 0.007-inch undersize. A cut that removes more than 0.007 inch places too much load on the reamer and should not be attempted.

Reamers are made of either carbon tool steel or high-speed steel. The cutting blades of a high-speed steel reamer lose their original keenness sooner than those of a carbon steel reamer; however, after the first super-keenness is gone, they are still serviceable. The high-speed reamer usually lasts much longer than the carbon steel type.

Milli-Meter	Dec. Equiv.	Frac. Num-ber	Milli-Meter	Dec. Equiv.	Frac. Num-ber	Milli-Meter	Dec. Equiv.	Frac. Num-ber	Milli-Meter	Dec. Equiv.	Frac. Num-ber	Milli-Meter	Dec. Equiv.	Frac. Num-ber	
.1	.0039		1.75	.0689	1570	22	6.8	.2677		10.72	.4219	27/64	
.15	.0059	0700	50	4.0	.1575		6.9	.2716		11.0	.4330		
.2	.0079		1.8	.0709	1590	212720	I	11.11	.4375	7/16	
.25	.0098		1.85	.0728	1610	20	7.0	.2756		11.5	.4528		
.3	.0118	0730	49	4.1	.1614	2770	J	11.51	.4531	29/64	
.....	.0135	80	1.9	.0748		4.2	.1654		7.1	.2795		11.91	.4687	15/32	
.35	.0138	0760	481660	192811	K	12.0	.4724		
.....	.0145	79	1.95	.0767		4.25	.1673		7.14	.2812	9/32	12.30	.4843	31/64
.39	.0156	1/64	1.98	.0781	5/64	4.3	.1693		7.2	.2835		12.5	.4921		
.4	.0157	0785	471695	18	7.25	.2854		12.7	.5000	1/2	
.....	.0160	78	2.0	.0787		4.37	.1719	11/642874		13.0	.5118		
.45	.0177		2.05	.0807	1730	172900	L	13.10	.5156	33/64	
.....	.0180	770810	46	4.4	.1732		7.4	.2913		13.49	.5312	17/32	
.5	.0197	0820	451770	162950	M	13.5	.5315		
.....	.0200	76	2.1	.0827		4.5	.1771		7.5	.2953		13.89	.5469	35/64	
.....	.0210	75	2.15	.0846	1800	15	7.54	.2968	19/64	14.0	.5512	
.55	.0217	0860	44	4.6	.1811		7.6	.2992		14.29	.5625	9/16	
.....	.0225	74	2.2	.0866	1820	143020	N	14.5	.5709		
.6	.0236		2.25	.0885		4.7	.1850		7.7	.3031		14.68	.5781	37/64	
.....	.0240	730890	43	4.75	.1870		7.75	.3051		15.0	.5906		
.....	.0250	72	2.3	.0905		4.76	.1875	3/163071		15.08	.5937	19/32	
.65	.0256		2.35	.0925		4.8	.1890		7.9	.3110		15.48	.6094	39/64	
.....	.0260	710935	421910	11	7.94	.3125	5/16	15.5	.6102	
.....	.0280	70	2.38	.0937	3/32	4.9	.1929		8.0	.3150		15.88	.6250	5/8	
.7	.0276		2.4	.0945	1935	103160	O	16.0	.6299		
.....	.0292	690960	411960	9	8.1	.3189		16.27	.6406	41/64	
.75	.0295		2.45	.0964		5.0	.1968		8.2	.3228		16.5	.6496		
.....	.0310	680980	401990	83230	P	16.67	.6562	21/32	
.79	.0312	1/32	2.5	.0984		5.1	.2008		8.25	.3248		17.0	.6693		
.8	.0315	0995	392010	7	8.3	.3268		17.06	.6719	43/64	
.....	.0320	671015	38	5.16	.2031	13/64	8.33	.3281	21/64	17.46	.6875	11/16
.....	.0330	66	2.6	.1024	2040	6	8.4	.3307		17.5	.6890		
.85	.0335	1040	37	5.2	.2047	3320	Q	17.86	.7031	45/64	
.....	.0350	65	2.7	.1063	2055	5	8.5	.3346		18.0	.7087		
.9	.0354	1065	36	5.25	.2067		8.6	.3386		18.26	.7187	23/32	
.....	.0360	64	2.75	.1082		5.3	.2086	3390	R	18.5	.7283		
.....	.0370	63	2.78	.1094	7/642090	4	8.7	.3425		18.65	.7344	47/64	
.95	.0374	1100	35	5.4	.2126		8.73	.3437	11/32	19.0	.7480	
.....	.0380	62	2.8	.1102	2130	3	8.75	.3445		19.05	.7500	3/4	
.....	.0390	611110	34	5.5	.2165		8.8	.3465		19.45	.7656	49/64	
1.0	.0394	1130	33	5.56	.2187	1/323480	S	19.5	.7677		
.....	.0400	60	2.9	.1141		5.6	.2205		8.9	.3504		19.84	.7812	25/32	
.....	.0410	591160	322210	2	9.0	.3543		20.0	.7874		
1.05	.0413		3.0	.1181		5.7	.2244	3580	T	20.24	.7969	51/64	
.....	.0420	581200	31	5.75	.2263		9.1	.3583		20.5	.8071		
.....	.0430	57	3.1	.1220	2280	1	9.13	.3594	23/64	20.64	.8125	13/16
1.1	.0433		3.18	.1250	1/82283		9.2	.3622		21.0	.8268		
1.15	.0452		3.2	.1260		5.9	.2323		9.25	.3641		21.03	.8281	53/64	
.....	.0465	56	3.25	.1279	2340	A	9.3	.3661		21.43	.8437	27/32	
1.19	.0469	3/641285	30	5.95	.2344	15/643680	U	21.5	.8465		
1.2	.0472		3.3	.1299		6.0	.2362		9.4	.3701		21.83	.8594	55/64	
1.25	.0492		3.4	.1338	2380	B	9.5	.3740		22.0	.8661		
1.3	.0512	1360	29	6.1	.2401		9.53	.3750	3/8	22.23	.8750	7/8
.....	.0520	55	3.5	.1378	2420	C3770	V	22.5	.8858		
1.35	.0531	1405	28	6.2	.2441		9.6	.3780		22.62	.8906	57/64	
.....	.0550	54	3.57	.1406	9/642460	D	9.7	.3819		23.0	.9055		
1.4	.0551		3.6	.1417		6.3	.2480		9.75	.3838		23.02	.9062	29/32	
1.45	.0570	1440	27	6.35	.2500	1/4	9.8	.3858		23.42	.9219	59/64	
1.5	.0591		3.7	.1457	2520	E3860	W	23.5	.9252		
.....	.0595	531470	26	6.5	.2559		9.9	.3898		23.81	.9375	15/16	
1.55	.0610		3.75	.1476	2570	F	9.92	.3906	25/64	24.0	.9449	
1.59	.0625	1/161495	25	6.6	.2598		10.0	.3937		24.21	.9531	61/64	
1.6	.0629		3.8	.1496	2610	G3970	X	24.5	.9646		
.....	.0635	521520	24	6.7	.2638	4040	Y	24.61	.9687	31/32	
1.65	.0649		3.9	.1535		6.75	.2657	17/64	10.32	.4062	13/32	25.0	.9843	
1.7	.0669	1540	23	6.75	.2657	4130	Z	25.03	.9844	63/64	
.....	.0670	51	3.97	.1562	5/322660	H	10.5	.4134		25.4	1.0000	1	

FIGURE 12-15. Drill sizes.




FIGURE 12-16. Drill sharpening procedures.




FIGURE 12-17. Reamers.

Reamer blades are hardened to the point of being brittle and must be handled carefully to avoid chipping them. When reaming a hole, rotate the reamer in the cutting direction only. Turn the reamer steadily and evenly to prevent chattering, or marking and scoring of the hole walls.

Reamers are available in any standard size. The straight-fluted reamer is less expensive than the spiral-fluted reamer, but the spiral type has less tendency to chatter. Both types are tapered for a short distance back of the end to aid in starting. Bottoming reamers have no taper and are used to complete the reaming of blind holes.

For general use, an expansion reamer is the most practical. This type is furnished in standard sizes from $\frac{1}{4}$ inch to 1 inch, increasing in diameter by $\frac{1}{32}$ -inch increments.

Taper reamers, both hand- and machine-operated, are used to smooth and true tapered holes and recesses.

Countersink

A countersink is a tool which cuts a cone-shaped depression around the hole to allow a rivet or screw to set flush with the surface of the material. Countersinks are made with various angles to correspond to the various angles of the




FIGURE 12-18. Countersinks.

countersunk rivet and screwheads. The angle of the standard countersink shown in figure 12-18 is 100°.

Special stop countersinks are available. Stop countersinks (figure 12-18) are adjustable to any desired depth, and the cutters are interchangeable so that holes of various countersunk angles may be made. Some stop countersinks have a micrometer set arrangement (in increments of 0.001 inch) for adjusting the cutting depths.

When using a countersink, care must be taken not to remove an excessive amount of material since this reduces the strength of flush joints.

LAYOUT AND MEASURING TOOLS

Layout and measuring devices are precision tools. They are carefully machined, accurately marked and, in many cases, are made up of very delicate parts. When using these tools, be careful not to drop, bend, or scratch them. The finished product will be no more accurate than the measurements or the layout; therefore, it is very important to understand how to read, use, and care for these tools.

Rules

Rules are made of steel and are either rigid or flexible. The flexible steel rule will bend, but it should not be bent intentionally as it may be broken rather easily.

In aircraft work the unit of measure most commonly used is the inch. The inch may be divided into smaller parts by means of either common or decimal fraction divisions. The frac-




FIGURE 12-19. Rules.




FIGURE 12-20. Combination set.

tional divisions for an inch are found by dividing the inch into equal parts—halves ($\frac{1}{2}$), quarters ($\frac{1}{4}$), eighths ($\frac{1}{8}$), sixteenths ($\frac{1}{16}$), thirty-seconds ($\frac{1}{32}$), and sixty-fourths ($\frac{1}{64}$)—as shown in figure 12-17.

The fractions of an inch may be expressed in decimals, called decimal equivalents of an inch; for example, $\frac{1}{8}$ inch is expressed as 0.0125 (one hundred twenty-five ten-thousandths of an inch).

Rules are manufactured in two basic styles, those divided or marked in common fractions (figure 12-19) and those divided or marked in decimals or divisions of one one-hundredth of an inch. A rule may be used either as a measuring tool or as a straightedge.

Combination Sets

The combination set (figure 12-20), as its name implies, is a tool that has several uses. It can be used for the same purposes as an ordinary tri-square, but it differs from the tri-square in that the head slides along the blade and can be clamped at any desired place. Combined with the square or stock head are a level and scribe. The head slides in a central groove on the blade or scale, which can be used separately as a rule.

The spirit level in the stock head makes it convenient to square a piece of material with a surface and at the same time tell whether one or the other is plumb or level. The head can be used alone as a simple level.

The combination of square head and blade can also be used as a marking gage to scribe lines at a 45° angle, as a depth gage, or as a height gage.

A convenient scribe is held frictionally in the head by a small brass bushing.

The center head is used to find the center of shafts or other cylindrical work. The protractor head can be used to check angles and also may be set at any desired angle to draw lines.

Scriber

The scriber is designed to serve the aviation mechanic in the same way a pencil or pen serves a writer. In general, it is used to scribe or mark lines on metal surfaces. The scriber (figure 12-21) is made of tool steel, 4 to 12 inches long, and has two needle-pointed ends. One end is bent at a 90° angle for reaching and marking through holes.

Before using a scriber always inspect the points for sharpness. Be sure the straightedge is flat on the metal and in position for scribing. Tilt the scriber slightly in the direction toward which it will be moved, holding it like a pencil. Keep the scriber's point close to the guiding edge of the straightedge. The scribed line should be heavy enough to be visible, but no deeper than necessary to serve its purpose.



FIGURE 12-21. Scriber.

Dividers and Pencil Compasses

Dividers and pencil compasses have two legs joined at the top by a pivot. They are used to scribe circles and arcs and for transferring measurements from the rule to the work.

Pencil compasses have one leg tapered to a needle point; the other leg has a pencil or pencil lead inserted. Dividers have both legs tapered to needle points.

When using pencil compasses or dividers, the following procedures are suggested:

1. Inspect the points to make sure they are sharp.
2. To set the dividers or compasses, hold them with the point of one leg in the graduations on the rule. Turn the adjustment nut with the thumb and forefinger; adjust the dividers or compasses until the point of the other leg rests on the graduation of the rule which gives the required measurement.
3. To draw an arc or circle with either the pencil compasses or dividers, hold the thumb attachment on the top with the thumb and forefinger. With pressure exerted on both legs, swing the compass in a clockwise direction and draw the desired arc or circle.
4. The tendency for the legs to slip is avoided by inclining the compasses or dividers in the direction in which they are being rotated. In working on metals, the dividers are used only to scribe arcs or circles that will later be removed by cutting. All other arcs or circles are drawn with pencil compasses to avoid scratching the material.
5. On paper layouts, the pencil compasses are used for describing arcs and circles. Dividers should be used to transfer critical measurements because they are more accurate than a pencil compass.

Calipers

Calipers are used for measuring diameters and distances or for comparing distances and sizes. The three common types of calipers are the inside, the outside, and the hermaphrodite calipers, such as gear-tool calipers. (See figure 12-22.)

Outside calipers are used for measuring outside dimensions, for example, the diameter of a piece of




FIGURE 12-22. Calipers.

round stock. Inside calipers have outward curved legs for measuring inside diameters, such as diameters of holes, the distance between two surfaces, the width of slots, and other similar jobs. A hermaphrodite caliper is generally used as a marking gage in layout work. It should not be used for precision measurement.

Micrometer Calipers

There are four types of micrometer calipers, each designed for a specific use. The four types are




FIGURE 12-23. Outside micrometer.

commonly called outside micrometer, inside micrometer, depth micrometer, and thread micrometer. Micrometers are available in a variety of sizes, either 0 to $\frac{1}{2}$ inch, 0 to 1 inch, 1 to 2 inch, 2 to 3 inch, 3 to 4 inch, 4 to 5 inch, or 5 to 6 inch sizes.

The outside micrometer (figure 12-23) is used by the mechanic more often than any other type. It may be used to measure the outside dimensions of shafts, thickness of sheet metal stock, diameter of drills, and for many other applications.

The smallest measurement which can be made with the use of the steel rule is one sixty-fourth of an inch in common fractions, and one one-hundredth of an inch in decimal fractions. To measure more closely than this (in thousandths and ten-thousandths of an inch), a micrometer is used. If a dimension given in a common fraction is to be measured with the micrometer, the fraction must be converted to its decimal equivalent.

All four types of micrometers are read in the same way. The method of reading an outside micrometer is discussed later in this chapter.

Micrometer Parts

The fixed parts of a micrometer (figure 12-23) are the frame, barrel, and anvil. The movable parts of a micrometer are the thimble and spindle. The thimble rotates the spindle which moves in the threaded portion inside the barrel. Turning the thimble provides an opening between the anvil and the end of the spindle where the work is measured. The size of the work is indicated by the graduations on the barrel and thimble.

Reading a Micrometer

The lines on the barrel marked 1, 2, 3, 4, etc., indicate measurements of tenths, or 0.100 inch, 0.200 inch, 0.300 inch, 0.400 inch, respectively (see figure 12-24).

Each of the sections between the tenths divisions (between 1, 2, 3, 4, etc.) is divided into four parts of 0.025 inch each. One complete revolution of the thimble (from zero on the thimble around to the same zero) moves it one of these divisions (0.025 inch) along the barrel.

The bevel edge of the thimble is divided into 25 equal parts. Each of these parts represents one twenty-fifth of the distance the thimble travels along the barrel in moving from one of the 0.025-inch divisions to another. Thus, each division on the thimble represents one one-thousandth (0.001) of an inch. These divisions are marked for convenience at every five spaces by 0, 5, 10, 15,







FIGURE 12-24. Micrometer measurements.




(A) .150 in.



(B) .151 in.



(C) .160 in.



(D) .175 in.

FIGURE 12-25. Reading a micrometer.


and 20. When 25 of these graduations have passed the horizontal line on the barrel, the spindle (having made one revolution) has moved 0.025 inch.

The micrometer is read by first noting the last visible figure on the horizontal line of the barrel representing tenths of an inch. Add to this the length of barrel between the thimble and the previously noted number. (This is found by multiplying the number of graduations by 0.025 inch.) Add to this the number of divisions on the bevel edge of the thimble that coincides with the line of the graduation. The total of the three figures equals the measurement. (Figure 12-25 shows several sample readings.)

Vernier Scale


Some micrometers are equipped with a vernier scale which makes it possible to read directly the fraction of a division that may be indicated on the thimble scale. Typical examples of the vernier scale as it applies to the micrometer are shown in figure 12-26.

All three scales on a micrometer are not fully visible without turning the micrometer; but the examples shown in figure 12-26 are drawn as though the barrel and thimble of the micrometer were laid out flat so that all three scales can be seen at the same time. The barrel scale is the lower horizontal scale; the thimble scale is vertical on the right; and the long horizontal lines (0 through 9 and 0) make up the vernier scale.



0.2944

0.2947



0.2153

0.1005

FIGURE 12-26. Vernier scale readings.

In reading a micrometer, an excellent way to remember the relative scale values is to remember that the 0.025-inch barrel scale graduations are established by the lead screw (40 threads per inch). Next, the thimble graduations divide the 0.025 inch into 25 parts, each equal to 0.001 inch; then the vernier graduations divide the 0.001 inch into 10 equal parts, each equal to 0.0001 inch. Remembering the values of the various scale graduations, the barrel scale reading is noted. The thimble scale reading is added to it; then the vernier scale reading is added to get the final reading. The vernier scale line to be read is always the one aligned exactly with any thimble graduation.

In the first example in figure 12-26, the barrel reads 0.275 inch and the thimble reads more than 0.019 inch. The number 1 graduation on the thimble is aligned exactly with the number 4 graduation on the vernier scale. Thus, the final reading is 0.2944 inch.

In the second example in figure 12-26, the barrel reads 0.275 inch, and the thimble reads more than 0.019 inch and less than 0.020 inch. On the vernier scale, the number 7 graduation coincides with a line on the thimble. This means that the thimble reading would be 0.0197 inch. Adding this to the barrel reading of 0.275 inch gives a total measurement of 0.2947 inch.

The third and fourth examples in figure 12-26 are additional readings that would require use of the vernier scale for accurate readings to ten-thousandths of an inch.

Using a Micrometer

The micrometer must be handled carefully. If it is dropped, its accuracy may be permanently affected. Continually sliding work between the






FIGURE 12-27. Hand taps.



Adjusting screw

A Adjustable round split die



B Plain round split die

FIGURE 12-28. Types of dies.

anvil and spindle may wear the surfaces. If the spindle is tightened too much, the frame may be sprung permanently and inaccurate readings will result.

To measure a piece of work with the micrometer, hold the frame of the micrometer in the palm of the hand with the little finger or third finger, whichever is more convenient. This allows the thumb and forefinger to be free to revolve the thimble for adjustment.

TAPS AND DIES

A tap is used to cut threads on the inside of a hole, while a die is for cutting external threads on round stock. They are made of hard-tempered steel and ground to an exact size. There are four types of threads that can be cut with standard taps and dies. They are: National Coarse, National Fine, National Extra Fine, and National Pipe.

Hand taps are usually provided in sets of three taps for each diameter and thread series. Each set contains a taper tap, a plug tap, and a bottoming tap. The taps in a set are identical in diameter and cross section; the only difference is the amount of taper (see figure 12-27).

The taper tap is used to begin the tapping process, because it is tapered back for 6 to 7 threads. This tap cuts a complete thread when it is cutting above the taper. It is the only tap needed when tapping holes that extend through thin sections. The plug tap supplements the taper tap for tapping holes in thick stock.




FIGURE 12-29. Diestock and tap wrenches.

The bottoming tap is not tapered. It is used to cut full threads to the bottom of a blind hole.

Dies may be classified as adjustable round split die, and plain round split die (see figure 12-28). The adjustable-split die has an adjusting screw that can be tightened so that the die is spread slightly. By adjusting the die, the diameter and fit of the thread can be controlled.

Solid dies are not adjustable; therefore, a variety of thread fits cannot be obtained with this type.

There are many types of wrenches for turning taps, as well as turning dies. The T-handle, the adjustable tap wrench, and the diestock for round split dies shown in figure 12-29 are a few of the more common types.

Information on thread sizes, fits, types, etc., is shown in figs. 12-30, 12-31 and 12-32.

NATIONAL COARSE THREAD SERIES MEDIUM FIT. CLASS 3 (NC)					NATIONAL FINE THREAD SERIES MEDIUM FIT. CLASS 3 (NF)				
Size and Threads	Dia. of body for thread	Body Drill	Tap Drill		Size and threads	Dia. of body for thread	Body Drill	Tap Drill	
			Pref'd dia. of hole	Nearest stand'd Drill Size				Pref'd dia. of hole	Nearest stand'd Drill Size
					0-80	.060	52	.0472	3/64
1-64	.073	47	.0575	#53	1-72	.073	47	.0591	#53
2-56	.086	42	.0682	#51	2-64	.086	42	.0700	#50
3-48	.099	37	.078	5/64	3-56	.099	37	.0810	#46
4-40	.112	31	.0866	#44	4-48	.112	31	.0911	#42
5-40	.125	29	.0995	#39	5-44	.125	25	.1024	#38
6-32	.138	27	.1063	#36	6-40	.138	27	.113	#33
8-32	.164	18	.1324	#29	8-36	.164	18	.136	#29
10-24	.190	10	.1472	#26	10-32	.190	10	.159	#21
12-24	.216	2	.1732	#17	12-28	.216	2	.180	#15
1/4-20	.250	1/4	.1990	#8	1/4-28	.250	F	.213	#3
5/16-18	.3125	5/16	.2559	#F	5/16-24	.3125	5/16	.2703	I
3/8-16	.375	3/8	.3110	5/16"	3/8-24	.375	3/8	.332	Q
7/16-14	.4375	7/16	.3642	U	7/16-20	.4375	7/16	.386	W
1/2-13	.500	1/2	.4219	27/64"	1/2-20	.500	1/2	.449	7/16"
9/16-12	.5625	9/16	.4776	31/64"	9/16-18	.5625	9/16	.506	1/2"
5/8-11	.625	5/8	.5315	17/32"	5/8-18	.625	5/8	.568	9/16"
3/4-10	.750	3/4	.6480	41/64"	3/4-16	.750	3/4	.6688	11/16"
7/8-9	.875	7/8	.7307	49/64"	7/8-14	.875	7/8	.7822	51/64"
1-8	1.000	1.0	.8376	7/8"	1-14	1.000	1.0	.9072	49/64"

FIGURE 12-30. American (National) screw thread sizes.

Nominal Size Inches	No. of Threads per Inch	Pitch Diameter		Length		Pipe O. D. D Inches	Depth of Thread Inches	Tap Drills for Pipe Threads	
		A Inches	B Inches	L2 Inches	L1 Inches			Minor Diameter Small End of Pipe	Size Drill
1/4	18	.47739	.48989	.4018	.200	.540	.04444	.43294	7/16
3/8	18	.61201	.62701	.4078	.240	.675	.04444	.56757	37/64
1/2	14	.75843	.77843	.5337	.320	.840	.05714	.70129	23/32
3/4	14	.96768	.98887	.5457	.339	1.050	.05714	.91054	59/64
1	11-1/2	1.21363	1.23863	.6828	.400	1.315	.06957	1.14407	1-5/32
1-1/4	11-1/2	1.55713	1.58338	.7068	.420	1.660	.06957	1.48757	1-1/2
1-1/2	11-1/2	1.79609	1.82234	.7235	.420	1.900	.06957	1.72652	1-47/64
2	11-1/2	2.26902	2.29627	.7565	.436	2.375	.06957	2.19946	2-7/32
2-1/2	8	2.71953	2.76216	1.1375	.682	2.875	.10000	2.61953	2-5/8
3	8	3.34062	3.38850	1.2000	.766	3.500	.10000	3.24063	3-1/4
3-1/2	8	3.83750	3.88881	1.2500	.821	4.000	.10000	3.73750	3-3/4
4	8	4.33438	4.38712	1.3000	.844	4.500	.10000	4.23438	4-1/4

FIGURE 12-31. American (National) pipe thread dimensions and tap drill sizes.

Diameter of Drill	Soft Metals 300 F.P.M.	Plastics and Hard Rubber 200 F.P.M.	Annealed Cast Iron 140 F.P.M.	Mild Steel 100 F.P.M.	Malleable Iron 90 F.P.M.	Hard Cast Iron 80 F.P.M.	Tool or Hard Steel 60 F.P.M.	Alloy Steel Cast Steel 40 F.P.M.
1/16 (No. 53 to 80)	18320	12217	8554	6111	5500	4889	3667	2445
3/32 (No. 42 to 52)	12212	8142	5702	4071	3666	3258	2442	1649
1/8 (No. 31 to 41)	9160	6112	4278	3056	2750	2445	1833	1222
5/32 (No. 23 to 30)	7328	4888	3420	2444	2198	1954	1465	977
3/16 (No. 13 to 22)	6106	4075	2852	2037	1833	1630	1222	815
7/32 (No. 1 to 12)	5234	3490	2444	1745	1575	1396	1047	698
1/4 (A to E)	4575	3055	2139	1527	1375	1222	917	611
9/32 (C to K)	4071	2712	1900	1356	1222	1084	814	542
9/16 (L, M, N)	3660	2445	1711	1222	1100	978	733	489
11/32 (O to R)	3330	2220	1554	1110	1000	888	666	444
3/8 (S, T, U)	3050	2037	1426	1018	917	815	611	407
13/32 (V to Z)	2818	1878	1316	939	846	752	563	376
7/16	2614	1746	1222	873	786	698	524	349
15/32	2442	1628	1140	814	732	652	488	326
1/2	2287	1528	1070	764	688	611	458	306
9/16	2035	1357	950	678	611	543	407	271
3/8	1830	1222	856	611	550	489	367	244
11/16	1665	1110	777	555	500	444	333	222
3/4	1525	1018	713	509	458	407	306	204

Figures are for High-Speed Drills. The speed of Carbon Drills should be reduced one-half. Use drill speed nearest to figure given.

FIGURE 12-32. Drill speeds.